



SORIANI s.r.l.

Bulletin No: 2019_AR02

Release Date: March 15, 2019

Effective Date: May 15, 2019

Supersedes:

Completion Date: Before 2019 operating season.

Page: 1 of 25

SERVICE BULLETIN

Ride Manufacturer: Soriani Srl

Affected Production Dates: 2011

Ride Name: Air Race 8.2 T/M

Affected Serial Nos.: 392GAR16R11339US

Model Number: Air Race 8.2 T/M

Abstract Of Issue:

Additional preventive maintenance test procedure for restraint cylinder (part numbers 15300705201, 15300705401, 0400902000001 and 0400902000002).

Reason For Release:

To distribute the guidelines to all Owners for additional preventive maintenance test procedure for the restraint cylinders.

Action To Be Taken:

Add attached manual pages to the Use and Maintenance Manual. Update accordingly the Owner's preventive maintenance procedures.

Detail Of Issue:

Attached.

Future Action To Be Taken:

Replacement of Hydraulic cylinders every 7 years. If cylinders pass the attached test, they may be used for the 2019 season. Cylinders that are older than 7 years must be replaced prior to the 2020 operating season.

Note for ordering parts:

Part number 0400902000001 supersedes 15300705201.

Part number 0400902000002 supersedes 15300705401.