

<p>ZAMPERLA INC. 49 Fanny Road Parsippany, New Jersey 07054-6545 USA Phone: 973 334 8133 Fax: 973 334 6880</p>	Bulletin No: 2003 MJ01
	Release Date: February 28, 2003
	Effective Date: February 28, 2003
	Supersedes:
	Completion Date: As soon as possible
Page: 1 of 2	

SERVICE BULLETIN

Ride Manufacturer: Zamperla Inc.	Affected Production Dates: All Mini Jet Crop Duster rides
Ride Name: Mini Jet Crop Duster	Affected Serial Nos.: 98310,98320,98327,98374,98395
Model Number: Mini Jet Crop Duster	

Abstract Of Issue:

A crack has been detected in a weld of a sweep arm.

Reason For Release:

A crack has been developed on the ride.

Action To Be Taken:

Visually inspect the welds on the sweep arms of the ride.
If there are any signs of a crack, remove the paint and perform a dye penetrant test.
Notify Zamperla for a repair procedure if a crack has been detected and confirmed.

Detail Of Issue:

Diagram of sweep arm with area indicated (Page 2 of 2)
The area for inspection is the weld of the upper fish plate.

Future Action To Be Taken:

Visually inspection the area on a monthly basis.

