

Ride distributed by:
Zamperla, Inc.
49 Fanny Road
Boonton, NJ 07005
USA
Phone: 973.334.8133
Fax: 973.334.6880
email: zamperla@zamperlausa.com



Bulletin No: 12-MJ01
Release Date: 22 August 2012
Effective Date: 22 August 2012
Supersedes: n/a
Completion Date: 22 August 2012

Page: 1 of 2

SERVICE BULLETIN

Ride Manufacturer: A. Zamperla SpA	Affected Production Dates: Before January 1 1996
Ride Name: Mini Jet	Affected Serial Nos.: All models in the Mini Jet family
Model Number: Mini Jet	manufactured prior to January 1 1996

Abstract Of Issue:

There is a potential for a crack in the area of the weld of the sweep arm - fork.

Reason For Release:

Same.

Weekly perform visual inspection on the welds of the sweep arms - fork of the ride.
Annually perform a non-destructive test (NDT) by means of magnetic particle according to ASTM E709,
EN 1290 or equivalent
Notify Zamperla if a crack exists in the weld.

Detail Of Issue:

Diagram of the zone with area indicated (Page 2 of 2)

Future Action To Be Taken:

Follow this maintenance and inspection procedure in the instruction manual.

